

## STM32C031x4/x6 device errata

## Applicability

This document applies to the part numbers of STM32C031x4/x6 devices and the device variants as stated in this page.

It gives a summary and a description of the device errata, with respect to the device datasheet and reference manual RM0490.

Deviation of the real device behavior from the intended device behavior is considered to be a device limitation. Deviation of the description in the reference manual or the datasheet from the intended device behavior is considered to be a documentation erratum. The term “*errata*” applies both to limitations and documentation errata.

**Table 1. Device summary**

Reference	Part numbers
STM32C031xx	STM32C031C4, STM32C031C6, STM32C031F4, STM32C031F6, STM32C031G4, STM32C031G6, STM32C031K4, STM32C031K6

**Table 2. Device variants**

Reference	Silicon revision codes	
	Device marking <sup>(1)</sup>	REV_ID <sup>(2)</sup>
STM32C031xx	A	0x1000
	Z	0x1001

1. Refer to the device datasheet for how to identify this code on different types of package.

2. REV\_ID[15:0] bitfield of DBGMCU\_IDCODE register.

# 1 Summary of device errata

The following table gives a quick reference to the STM32C031x4/x6 device limitations and their status:

A = limitation present, workaround available

N = limitation present, no workaround available

P = limitation present, partial workaround available

“-” = limitation absent

Applicability of a workaround may depend on specific conditions of target application. Adoption of a workaround may cause restrictions to target application. Workaround for a limitation is deemed partial if it only reduces the rate of occurrence and/or consequences of the limitation, or if it is fully effective for only a subset of instances on the device or in only a subset of operating modes, of the function concerned.

**Table 3. Summary of device limitations**

Function	Section	Limitation	Status	
			Rev. A	Rev. Z
System	2.2.1	HSI48 clock fails to stop upon entering Stop mode	A	-
	2.2.2	PA11 Schmitt trigger remains effective in analog input mode	P	-
	2.2.3	Missed wakeup event coinciding with Stop entry	A	-
	2.2.4	A non-zero HSI48DIV[2:0] upon Stop entry may lead to a deadlock	A	-
	2.2.5	First SRAM access after reset fails	A	-
	2.2.6	PC14 cannot be used for HSE external clock on 48-pin packages	N	-
	2.2.7	PB0/1/2/10 does not support negative injection	N	-
	2.2.8	PC13 signal transitions disturb LSE	N	N
DMA	2.3.1	DMA disable failure and error flag omission upon simultaneous transfer error and global flag clear	A	A
DMAMUX	2.4.1	SOFx not asserted when writing into DMAMUX_CFR register	N	N
	2.4.2	OFx not asserted for trigger event coinciding with last DMAMUX request	N	N
	2.4.3	OFx not asserted when writing into DMAMUX_RGCFR register	N	N
	2.4.4	Wrong input DMA request routed upon specific DMAMUX_CxCR register write coinciding with synchronization event	A	A
ADC	2.5.1	Overrun flag is not set if EOC reset coincides with new conversion end	P	P
TIM	2.6.1	One-pulse mode trigger not detected in master-slave reset + trigger configuration	P	P
	2.6.2	Consecutive compare event missed in specific conditions	N	N
	2.6.3	Output compare clear not working with external counter reset	P	P
RTC	2.7.1	Calendar initialization may fail in case of consecutive INIT mode entry	A	A
	2.7.2	Alarm flag may be repeatedly set when the core is stopped in debug	N	N
	2.7.3	Loss of RTC calendar and configuration content upon system reset	N	N
I2C	2.8.1	Wrong data sampling when data setup time ( $t_{SU,DAT}$ ) is shorter than one I2C kernel clock period	P	P
	2.8.2	Spurious bus error detection in master mode	A	A
	2.8.3	OVR flag not set in underrun condition	N	N
	2.8.4	Transmission stalled after first byte transfer	A	A
	2.8.5	SDA held low upon SMBus timeout expiry in slave mode	A	A
USART	2.9.1	Anticipated end-of-transmission signaling in SPI slave mode	A	A

Function	Section	Limitation	Status	
			Rev. A	Rev. Z
USART	2.9.2	Data corruption due to noisy receive line	N	N
	2.9.3	Received data may be corrupted upon clearing the ABREN bit	A	A
	2.9.4	Noise error flag set while ONEBIT is set	N	N
SPI	2.10.1	BSY bit may stay high when SPI is disabled	A	A
	2.10.2	BSY bit may stay high at the end of data transfer in slave mode	A	A

## 2 Description of device errata

The following sections describe the errata of the applicable devices with Arm® core and provide workarounds if available. They are grouped by device functions.

*Note:* Arm is a registered trademark of Arm Limited (or its subsidiaries) in the US and/or elsewhere.

arm

### 2.1 Core

Reference manual and errata notice for the Arm® Cortex®-M0+ core revision r0p1 is available from <http://infocenter.arm.com>.

### 2.2 System

#### 2.2.1 HSI48 clock fails to stop upon entering Stop mode

##### Description

Upon entering Stop mode, all running clocks are expected to automatically stop, to save power. However, with LSI or LSE selected as system clock, the HSI48 oscillator continues running, which impacts power consumption.

##### Workaround

Disable the HSI48 oscillator before entering Stop mode.

#### 2.2.2 PA11 Schmitt trigger remains effective in analog input mode

##### Description

The input buffer Schmitt trigger on the PA11 GPIO unduly remains effective in analog input mode. This may lead to an increased power consumption when PA11 is left floating and/or when the input voltage on PA11 used as analog input is near the GPIO input thresholds.

##### Workaround

When PA11 is unused, apply a weak pull-up or pull-down device internally or externally to keep the input voltage far from the GPIO input thresholds.

#### 2.2.3 Missed wakeup event coinciding with Stop entry

##### Description

When a wakeup event occurs at the same time or one CPU cycle before the core requests to enter Stop mode, the event may be missed. The device then remains in Stop mode until the following wakeup event.

##### Workaround

Apply the following steps:

1. Clear the pending events to enter the WFE.
2. Configure both EXTI\_EMR1 and EXTI\_IMR1 simultaneously to allow the event controller to generate event and interrupt.

*Note:* The CPU has to clear the pending interrupt in the EXTI after waking up from WFE (EXTI\_RPR1 and EXTI\_FPR1).

The following table shows some examples:

Event and interrupt setup	SW setup	Interrupt clearing
EXTI_EMR1 = EVT1	EXTI_RTZR1 = EVT1	EXTI_RPR1 = EVT1
EXTI_IMR1 = EVT1	WFE	EXTI_FPR1 = EVT1

### 2.2.4 A non-zero HSIDIV[2:0] upon Stop entry may lead to a deadlock

#### Description

A non-zero value of the HSIDIV[2:0] bitfield upon entering Stop mode may cause a deadlock in which the device fails to wake up.

#### Workaround

Write HSIDIV[2:0] with 0x0 before entering Stop mode and restore the former value upon wakeup.

### 2.2.5 First SRAM access after reset fails

#### Description

When asynchronous system reset occurs in a critical phase of SRAM write access, the SRAM controller remains in a state that causes the first SRAM access after the asynchronous system reset to fail. Any further SRAM accesses operate as expected.

As the probability of occurrence is extremely low, the failure is rare and difficult to reproduce.

#### Workaround

Always perform a dummy SRAM access after reset, such as:

```
MOV32 R0, #0x20000000 //set SRAM address
LDR R1, [R0, #+0] //read access
```

### 2.2.6 PC14 cannot be used for HSE external clock on 48-pin packages

#### Description

With the HSE\_NOT\_REMAPPED bit of the FLASH\_OTPR register cleared (HSE pins remapped from PF0/PF1 to PC14/PC15), the HSE oscillator bypass mode does not operate correctly on 48-pin packages. As a consequence, the PC14 pin cannot be used as HSE external clock input.

*Note:* The HSE oscillator bypass mode operates correctly with the HSE\_NOT\_REMAPPED bit set and the PF0 pin used as external HSE clock input.

#### Workaround

None.

### 2.2.7 PB0/1/2/10 does not support negative injection

#### Description

Negative injection above 0 mA on PB0/1/2/10 can lead to functional failure of the product.

#### Workaround

None.

### 2.2.8 PC13 signal transitions disturb LSE

#### Description

The PC13 port toggling disturbs the LSE clock.

**Workaround**

None.

**2.3 DMA**
**2.3.1 DMA disable failure and error flag omission upon simultaneous transfer error and global flag clear**
**Description**

Upon a data transfer error in a DMA channel x, both the specific TEIFx and the global GIFx flags are raised and the channel x is normally automatically disabled. However, if in the same clock cycle the software clears the GIFx flag (by setting the CGIFx bit of the DMA\_IFCR register), the automatic channel disable fails and the TEIFx flag is not raised.

This issue does not occur with ST's HAL software that does not use and clear the GIFx flag when the channel is active.

**Workaround**

Do not clear GIFx flags when the channel is active. Instead, use HTIFx, TCIFx, and TEIFx specific event flags and their corresponding clear bits.

**2.4 DMAMUX**
**2.4.1 SOFx not asserted when writing into DMAMUX\_CFR register**
**Description**

The SOFx flag of the DMAMUX\_CSR status register is not asserted if overrun from another DMAMUX channel occurs when the software writes into the DMAMUX\_CFR register.

This can happen when multiple DMA channels operate in synchronization mode, and when overrun can occur from more than one channel. As the SOFx flag clear requires a write into the DMAMUX\_CFR register (to set the corresponding CSOFx bit), overrun occurring from another DMAMUX channel operating during that write operation fails to raise its corresponding SOFx flag.

**Workaround**

None. Avoid the use of synchronization mode for concurrent DMAMUX channels, if at least two of them potentially generate synchronization overrun.

**2.4.2 OFx not asserted for trigger event coinciding with last DMAMUX request**
**Description**

In the DMAMUX request generator, a trigger event detected in a critical instant of the last-generated DMAMUX request being served by the DMA controller does not assert the corresponding trigger overrun flag OFx. The critical instant is the clock cycle at the very end of the trigger overrun condition.

Additionally, upon the following trigger event, one single DMA request is issued by the DMAMUX request generator, regardless of the programmed number of DMA requests to generate.

The failure only occurs if the number of requests to generate is set to more than two ( $GNBREQ[4:0] > 00001$ ).

**Workaround**

Make the trigger period longer than the duration required for serving the programmed number of DMA requests, so as to avoid the trigger overrun condition from occurring on the very last DMA data transfer.

### 2.4.3 OFx not asserted when writing into DMAMUX\_RGCFR register

#### Description

The OFx flag of the DMAMUX\_RGSR status register is not asserted if an overrun from another DMAMUX request generator channel occurs when the software writes into the DMAMUX\_RGCFR register. This can happen when multiple DMA channels operate with the DMAMUX request generator, and when an overrun can occur from more than one request generator channel. As the OFx flag clear requires a write into the DMAMUX\_RGCFR register (to set the corresponding COFx bit), an overrun occurring in another DMAMUX channel operating with another request generator channel during that write operation fails to raise the corresponding OFx flag.

#### Workaround

None. Avoid the use of request generator mode for concurrent DMAMUX channels, if at least two channels are potentially generating a request generator overrun.

### 2.4.4 Wrong input DMA request routed upon specific DMAMUX\_CxCR register write coinciding with synchronization event

#### Description

If a write access into the DMAMUX\_CxCR register having the SE bit at zero and SPOL[1:0] bitfield at a value other than 00:

- sets the SE bit (enables synchronization),
- modifies the values of the DMAREQ\_ID[5:0] and SYNC\_ID[4:0] bitfields, and
- does not modify the SPOL[1:0] bitfield,

and if a synchronization event occurs on the previously selected synchronization input exactly two AHB clock cycles before this DMAMUX\_CxCR write, then the input DMA request selected by the DMAREQ\_ID[5:0] value before that write is routed.

#### Workaround

Ensure that the SPOL[1:0] bitfield is at 00 whenever the SE bit is 0. When enabling synchronization by setting the SE bit, always set the SPOL[1:0] bitfield to a value other than 00 with the same write operation into the DMAMUX\_CxCR register.

## 2.5 ADC

### 2.5.1 Overrun flag is not set if EOC reset coincides with new conversion end

#### Description

If the EOC flag is cleared by an ADC\_DR register read operation or by software during the same APB cycle in which the data from a new conversion are written in the ADC\_DR register, the overrun event duly occurs (which results in the loss of either current or new data) but the overrun flag (OVR) may stay low.

#### Workaround

Clear the EOC flag, by performing an ADC\_DR read operation or by software within less than one ADC conversion cycle period from the last conversion cycle end, in order to avoid the coincidence with the end of the new conversion cycle.

## 2.6 TIM

### 2.6.1 One-pulse mode trigger not detected in master-slave reset + trigger configuration

#### Description

The failure occurs when several timers configured in one-pulse mode are cascaded, and the master timer is configured in combined reset + trigger mode with the MSM bit set:

OPM = 1 in TIMx\_CR1, SMS[3:0] = 1000 and MSM = 1 in TIMx\_SMCR.

The MSM delays the reaction of the master timer to the trigger event, so as to have the slave timers cycle-accurately synchronized.

If the trigger arrives when the counter value is equal to the period value set in the TIMx\_ARR register, the one-pulse mode of the master timer does not work and no pulse is generated on the output.

#### Workaround

None. However, unless a cycle-level synchronization is mandatory, it is advised to keep the MSM bit reset, in which case the problem is not present. The MSM = 0 configuration also allows decreasing the timer latency to external trigger events.

## 2.6.2 Consecutive compare event missed in specific conditions

### Description

Every match of the counter (CNT) value with the compare register (CCR) value is expected to trigger a compare event. However, if such matches occur in two consecutive counter clock cycles (as consequence of the CCR value change between the two cycles), the second compare event is missed for the following CCR value changes:

- in edge-aligned mode, from ARR to 0:
  - first compare event: CNT = CCR = ARR
  - second (missed) compare event: CNT = CCR = 0
- in center-aligned mode while up-counting, from ARR-1 to ARR (possibly a new ARR value if the period is also changed) at the crest (that is, when TIMx\_RCR = 0):
  - first compare event: CNT = CCR = (ARR-1)
  - second (missed) compare event: CNT = CCR = ARR
- in center-aligned mode while down-counting, from 1 to 0 at the valley (that is, when TIMx\_RCR = 0):
  - first compare event: CNT = CCR = 1
  - second (missed) compare event: CNT = CCR = 0

This typically corresponds to an abrupt change of compare value aiming at creating a timer clock single-cycle-wide pulse in toggle mode.

As a consequence:

- In toggle mode, the output only toggles once per counter period (squared waveform), whereas it is expected to toggle twice within two consecutive counter cycles (and so exhibit a short pulse per counter period).
- In center mode, the compare interrupt flag does not rise and the interrupt is not generated.

*Note:* The timer output operates as expected in modes other than the toggle mode.

#### Workaround

None.

## 2.6.3 Output compare clear not working with external counter reset

### Description

The output compare clear event (ocref\_clr) is not correctly generated when the timer is configured in the following slave modes: Reset mode, Combined reset + trigger mode, and Combined gated + reset mode.

The PWM output remains inactive during one extra PWM cycle if the following sequence occurs:

1. The output is cleared by the ocref\_clr event.
2. The timer reset occurs before the programmed compare event.

#### Workaround

Apply one of the following measures:



- Use BKIN (or BKIN2 if available) input for clearing the output, selecting the Automatic output enable mode (AOE = 1).
- Mask the timer reset during the PWM ON time to prevent it from occurring before the compare event (for example with a spare timer compare channel open-drain output connected with the reset signal, pulling the timer reset line down).

## 2.7 RTC

### 2.7.1 Calendar initialization may fail in case of consecutive INIT mode entry

#### Description

If the INIT bit of the RTC\_ICSR register is set between one and two RTCCLK cycles after being cleared, the INITF flag is set immediately instead of waiting for synchronization delay (which should be between one and two RTCCLK cycles), and the initialization of registers may fail. Depending on the INIT bit clearing and setting instants versus the RTCCLK edges, it can happen that, after being immediately set, the INITF flag is cleared during one RTCCLK period then set again. As writes to calendar registers are ignored when INITF is low, a write occurring during this critical period might result in the corruption of one or more calendar registers.

#### Workaround

After exiting the initialization mode, clear the BYPSHAD bit (if set) then wait for RSF to rise, before entering the initialization mode again.

*Note:* *It is recommended to write all registers in a single initialization session to avoid accumulating synchronization delays.*

### 2.7.2 Alarm flag may be repeatedly set when the core is stopped in debug

#### Description

When the core is stopped in debug mode, the clock is supplied to subsecond RTC alarm downcounter even when the device is configured to stop the RTC in debug.

As a consequence, when the subsecond counter is used for alarm condition (the MASKSS[3:0] bitfield of the RTC\_ALRMASR and/or RTC\_ALRMBSSR register set to a non-zero value) and the alarm condition is met just before entering a breakpoint or printf, the ALRAF and/or ALRBF flag of the RTC\_SR register is repeatedly set by hardware during the breakpoint or printf, which makes any attempt to clear the flag(s) ineffective.

#### Workaround

None.

### 2.7.3 Loss of RTC calendar and configuration content upon system reset

#### Description

The system reset unduly resets the RTC registers. As a consequence, the RTC calendar and the configuration contents are lost.

#### Workaround

None.

## 2.8 I2C

### 2.8.1 Wrong data sampling when data setup time ( $t_{SU, DAT}$ ) is shorter than one I2C kernel clock period

#### Description

The I<sup>2</sup>C-bus specification and user manual specify a minimum data setup time ( $t_{SU, DAT}$ ) as:

- 250 ns in Standard mode
- 100 ns in Fast mode
- 50 ns in Fast mode Plus

The device does not correctly sample the I<sup>2</sup>C-bus SDA line when  $t_{SU, DAT}$  is smaller than one I2C kernel clock (I<sup>2</sup>C-bus peripheral clock) period: the previous SDA value is sampled instead of the current one. This can result in a wrong receipt of slave address, data byte, or acknowledge bit.

#### Workaround

Increase the I2C kernel clock frequency to get I2C kernel clock period within the transmitter minimum data setup time. Alternatively, increase transmitter's minimum data setup time. If the transmitter setup time minimum value corresponds to the minimum value provided in the I<sup>2</sup>C-bus standard, the minimum I2CCLK frequencies are as follows:

- In Standard mode, if the transmitter minimum setup time is 250 ns, the I2CCLK frequency must be at least 4 MHz.
- In Fast mode, if the transmitter minimum setup time is 100 ns, the I2CCLK frequency must be at least 10 MHz.
- In Fast-mode Plus, if the transmitter minimum setup time is 50 ns, the I2CCLK frequency must be at least 20 MHz.

### 2.8.2 Spurious bus error detection in master mode

#### Description

In master mode, a bus error can be detected spuriously, with the consequence of setting the BERR flag of the I2C\_SR register and generating bus error interrupt if such interrupt is enabled. Detection of bus error has no effect on the I<sup>2</sup>C-bus transfer in master mode and any such transfer continues normally.

#### Workaround

If a bus error interrupt is generated in master mode, the BERR flag must be cleared by software. No other action is required and the ongoing transfer can be handled normally.

### 2.8.3 OVR flag not set in underrun condition

#### Description

In slave transmission with clock stretching disabled (NOSTRETCH = 1 in the I2C\_CR1 register), an underrun condition occurs if the current byte transmission is completed on the I<sup>2</sup>C bus, and the next data is not yet written in the TXDATA[7:0] bitfield. In this condition, the device is expected to set the OVR flag of the I2C\_ISR register and send 0xFF on the bus.

However, if the I2C\_TXDR is written within the interval between two I2C kernel clock cycles before and three APB clock cycles after the start of the next data transmission, the OVR flag is not set, although the transmitted value is 0xFF.

#### Workaround

None.

## 2.8.4 Transmission stalled after first byte transfer

### Description

When the first byte to transmit is not prepared in the TXDATA register, two bytes are required successively, through TXIS status flag setting or through a DMA request. If the first of the two bytes is written in the I2C\_TXDR register in less than two I2C kernel clock cycles after the TXIS/DMA request, and the ratio between APB clock and I2C kernel clock frequencies is between 1.5 and 3, the second byte written in the I2C\_TXDR is not internally detected. This causes a state in which the I2C peripheral is stalled in master mode or in slave mode, with clock stretching enabled (NOSTRETCH = 0). This state can only be released by disabling the peripheral (PE = 0) or by resetting it.

### Workaround

Apply one of the following measures:

- Write the first data in I2C\_TXDR before the transmission starts.
- Set the APB clock frequency so that its ratio with respect to the I2C kernel clock frequency is lower than 1.5 or higher than 3.

## 2.8.5 SDA held low upon SMBus timeout expiry in slave mode

### Description

For the slave mode, the SMBus specification defines  $t_{\text{TIMEOUT}}$  (detect clock low timeout) and  $t_{\text{LOW:SEXT}}$  (cumulative clock low extend time) timeouts. When one of them expires while the I2C peripheral in slave mode drives SDA low to acknowledge either its address or a data transmitted by the master, the device is expected to report such an expiry and release the SDA line.

However, although the device duly reports the timeout expiry, it fails to release SDA. This stalls the I<sup>2</sup>C bus and prevents the master from generating RESTART or STOP condition.

### Workaround

When a timeout is reported in slave mode (TIMEOUT bit of the I2C\_ISR register is set), apply this sequence:

1. Wait until the frame is expected to end.
2. Read the STOPF bit of the I2C\_ISR register. If it is low, reset the I2C kernel by clearing the PE bit of the I2C\_CR1 register.
3. Wait for at least three APB clock cycles before enabling again the I2C peripheral.

## 2.9 USART

### 2.9.1 Anticipated end-of-transmission signaling in SPI slave mode

#### Description

In SPI slave mode, at low USART baud rate with respect to the USART kernel and APB clock frequencies, the *transmission complete* flag TC of the USARTx\_ISR register may unduly be set before the last bit is shifted on the transmit line.

This leads to data corruption if, based on this anticipated end-of-transmission signaling, the application disables the peripheral before the last bit is transmitted.

#### Workaround

Upon the TC flag rise, wait until the clock line remains idle for more than the half of the communication clock cycle. Then only consider the transmission as ended.

## 2.9.2 Data corruption due to noisy receive line

### Description

In UART mode with oversampling by 8 or 16 and with 1 or 2 stop bits, the received data may be corrupted if a glitch to zero shorter than the half-bit occurs on the receive line within the second half of the stop bit.

### Workaround

None.

## 2.9.3 Received data may be corrupted upon clearing the ABREN bit

### Description

The USART receiver may miss data or receive corrupted data when the auto baud rate feature is disabled by software (ABREN bit cleared in the USART\_CR2 register) after an auto baud rate detection, while a reception is ongoing.

### Workaround

Do not clear the ABREN bit.

## 2.9.4 Noise error flag set while ONEBIT is set

### Description

When the ONEBIT bit is set in the USART\_CR3 register (one sample bit method is used), the noise error (NE) flag must remain cleared. Instead, this flag is set upon noise detection on the START bit.

### Workaround

None.

*Note: Having noise on the START bit is contradictory with the fact that the one sample bit method is used in a noise free environment.*

## 2.10 SPI

### 2.10.1 BSY bit may stay high when SPI is disabled

#### Description

The BSY flag may remain high upon disabling the SPI while operating in:

- master transmit mode and the TXE flag is low (data register full).
- master receive-only mode (simplex receive or half-duplex bidirectional receive phase) and an SCK strobing edge has not occurred since the transition of the RXNE flag from low to high.
- slave mode and NSS signal is removed during the communication.

#### Workaround

When the SPI operates in:

- master transmit mode, disable the SPI when TXE = 1 and BSY = 0.
- master receive-only mode, ignore the BSY flag.
- slave mode, do not remove the NSS signal during the communication.

## 2.10.2 BSY bit may stay high at the end of data transfer in slave mode

### Description

BSY flag may sporadically remain high at the end of a data transfer in slave mode. This occurs upon coincidence of internal CPU clock and external SCK clock provided by master.

In such an event, if the software only relies on BSY flag to detect the end of SPI slave data transaction (for example to enter low-power mode or to change data line direction in half-duplex bidirectional mode), the detection fails.

As a conclusion, the BSY flag is unreliable for detecting the end of data transactions.

### Workaround

Depending on SPI operating mode, use the following means for detecting the end of transaction:

- When NSS hardware management is applied and NSS signal is provided by master, use NSS flag.
- In SPI receiving mode, use the corresponding RXNE event flag.
- In SPI transmit-only mode, use the BSY flag in conjunction with a timeout expiry event. Set the timeout such as to exceed the expected duration of the last data frame and start it upon TXE event that occurs with the second bit of the last data frame. The end of the transaction corresponds to either the BSY flag becoming low or the timeout expiry, whichever happens first.

Prefer one of the first two measures to the third as they are simpler and less constraining.

Alternatively, apply the following sequence to ensure reliable operation of the BSY flag in SPI transmit mode:

1. Write last data to data register.
2. Poll the TXE flag until it becomes high, which occurs with the second bit of the data frame transfer.
3. Disable SPI by clearing the SPE bit mandatorily before the end of the frame transfer.
4. Poll the BSY bit until it becomes low, which signals the end of transfer.

*Note: The alternative method can only be used with relatively fast CPU speeds versus relatively slow SPI clocks or/and long last data frames. The faster is the software execution, the shorter can be the duration of the last data frame.*

## Important security notice

The STMicroelectronics group of companies (ST) places a high value on product security, which is why the ST product(s) identified in this documentation may be certified by various security certification bodies and/or may implement our own security measures as set forth herein. However, no level of security certification and/or built-in security measures can guarantee that ST products are resistant to all forms of attacks. As such, it is the responsibility of each of ST's customers to determine if the level of security provided in an ST product meets the customer needs both in relation to the ST product alone, as well as when combined with other components and/or software for the customer end product or application. In particular, take note that:

- ST products may have been certified by one or more security certification bodies, such as Platform Security Architecture ([www.psacertified.org](http://www.psacertified.org)) and/or Security Evaluation standard for IoT Platforms ([www.trustcb.com](http://www.trustcb.com)). For details concerning whether the ST product(s) referenced herein have received security certification along with the level and current status of such certification, either visit the relevant certification standards website or go to the relevant product page on [www.st.com](http://www.st.com) for the most up to date information. As the status and/or level of security certification for an ST product can change from time to time, customers should re-check security certification status/level as needed. If an ST product is not shown to be certified under a particular security standard, customers should not assume it is certified.
- Certification bodies have the right to evaluate, grant and revoke security certification in relation to ST products. These certification bodies are therefore independently responsible for granting or revoking security certification for an ST product, and ST does not take any responsibility for mistakes, evaluations, assessments, testing, or other activity carried out by the certification body with respect to any ST product.
- Industry-based cryptographic algorithms (such as AES, DES, or MD5) and other open standard technologies which may be used in conjunction with an ST product are based on standards which were not developed by ST. ST does not take responsibility for any flaws in such cryptographic algorithms or open technologies or for any methods which have been or may be developed to bypass, decrypt or crack such algorithms or technologies.
- While robust security testing may be done, no level of certification can absolutely guarantee protections against all attacks, including, for example, against advanced attacks which have not been tested for, against new or unidentified forms of attack, or against any form of attack when using an ST product outside of its specification or intended use, or in conjunction with other components or software which are used by customer to create their end product or application. ST is not responsible for resistance against such attacks. As such, regardless of the incorporated security features and/or any information or support that may be provided by ST, each customer is solely responsible for determining if the level of attacks tested for meets their needs, both in relation to the ST product alone and when incorporated into a customer end product or application.
- All security features of ST products (inclusive of any hardware, software, documentation, and the like), including but not limited to any enhanced security features added by ST, are provided on an "AS IS" BASIS. AS SUCH, TO THE EXTENT PERMITTED BY APPLICABLE LAW, ST DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, unless the applicable written and signed contract terms specifically provide otherwise.

## Revision history

Table 4. Document revision history

Date	Version	Changes
24-Mar-2022	1	Initial release.
19-Jul-2022	2	<p>Added Z device version and updated Table 2. Device variants and Table 3. Summary of device limitations</p> <p>Added errata:</p> <ul style="list-style-type: none"> <li>• <b>System:</b> PB0/1/2/10 does not support negative injection</li> <li>• PC13 signal transitions disturb LSE</li> </ul> <p>Added <a href="#">Section Important security notice</a> and information on core errata on Arm website.</p> <p>Removed errata (unduly inserted in the initial release):</p> <ul style="list-style-type: none"> <li>• <b>ADC:</b> <i>Writing ADC_CFGR1 register while ADEN bit is set resets RES[1:0] bitfield</i></li> <li>• <i>Out-of-threshold value is not detected in AWD1 Single mode</i></li> <li>• <b>I2C:</b> <i>Spurious master transfer upon own slave address match</i></li> <li>• <b>USART:</b> <i>USART prescaler feature missing in USART implementation section</i></li> </ul>
01-Dec-2022	3	<p>First public release.</p> <p>Added erratum <a href="#">SDA held low upon SMBus timeout expiry in slave mode</a> and updated Table 3. Summary of device limitations.</p>
22-Jun-2023	4	<p>Added errata:</p> <ul style="list-style-type: none"> <li>• <b>RTC:</b> <i>Loss of RTC calendar and configuration content upon system reset</i></li> <li>• <b>I2C:</b> <i>OVR flag not set in underrun condition</i></li> <li>• <i>Transmission stalled after first byte transfer</i></li> <li>• <b>USART:</b> <i>Anticipated end-of-transmission signaling in SPI slave mode</i></li> <li>• <i>Received data may be corrupted upon clearing the ABREN bit</i></li> <li>• <i>Noise error flag set while ONEBIT is set</i></li> </ul> <p>Removed erratum <a href="#">REFCKON write protection associated to INIT KEY instead of CAL KEY</a>.</p>

## Contents

<b>1</b>	<b>Summary of device errata</b>	<b>2</b>
<b>2</b>	<b>Description of device errata</b>	<b>4</b>
2.1	Core	4
2.2	System	4
2.2.1	HSI48 clock fails to stop upon entering Stop mode	4
2.2.2	PA11 Schmitt trigger remains effective in analog input mode	4
2.2.3	Missed wakeup event coinciding with Stop entry	4
2.2.4	A non-zero HSIDIV[2:0] upon Stop entry may lead to a deadlock	5
2.2.5	First SRAM access after reset fails	5
2.2.6	PC14 cannot be used for HSE external clock on 48-pin packages	5
2.2.7	PB0/1/2/10 does not support negative injection	5
2.2.8	PC13 signal transitions disturb LSE	5
2.3	DMA	6
2.3.1	DMA disable failure and error flag omission upon simultaneous transfer error and global flag clear	6
2.4	DMAMUX	6
2.4.1	SOFx not asserted when writing into DMAMUX_CFR register	6
2.4.2	OFx not asserted for trigger event coinciding with last DMAMUX request	6
2.4.3	OFx not asserted when writing into DMAMUX_RGCFR register	7
2.4.4	Wrong input DMA request routed upon specific DMAMUX_CxCR register write coinciding with synchronization event	7
2.5	ADC	7
2.5.1	Overrun flag is not set if EOC reset coincides with new conversion end	7
2.6	TIM	7
2.6.1	One-pulse mode trigger not detected in master-slave reset + trigger configuration	7
2.6.2	Consecutive compare event missed in specific conditions	8
2.6.3	Output compare clear not working with external counter reset	8
2.7	RTC	9
2.7.1	Calendar initialization may fail in case of consecutive INIT mode entry	9
2.7.2	Alarm flag may be repeatedly set when the core is stopped in debug	9
2.7.3	Loss of RTC calendar and configuration content upon system reset	9
2.8	I2C	10
2.8.1	Wrong data sampling when data setup time ( $t_{SU,DAT}$ ) is shorter than one I2C kernel clock period	10
2.8.2	Spurious bus error detection in master mode	10
2.8.3	OVR flag not set in underrun condition	10
2.8.4	Transmission stalled after first byte transfer	11



---

2.8.5	SDA held low upon SMBus timeout expiry in slave mode . . . . .	11
<b>2.9</b>	<b>USART . . . . .</b>	<b>11</b>
2.9.1	Anticipated end-of-transmission signaling in SPI slave mode . . . . .	11
2.9.2	Data corruption due to noisy receive line. . . . .	12
2.9.3	Received data may be corrupted upon clearing the ABREN bit. . . . .	12
2.9.4	Noise error flag set while ONEBIT is set . . . . .	12
<b>2.10</b>	<b>SPI . . . . .</b>	<b>12</b>
2.10.1	BSY bit may stay high when SPI is disabled . . . . .	12
2.10.2	BSY bit may stay high at the end of data transfer in slave mode. . . . .	13
<b>Important security notice . . . . .</b>		<b>14</b>
<b>Revision history . . . . .</b>		<b>15</b>

**IMPORTANT NOTICE – READ CAREFULLY**

STMicroelectronics NV and its subsidiaries (“ST”) reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST’s terms and conditions of sale in place at the time of order acknowledgment.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of purchasers’ products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. For additional information about ST trademarks, refer to [www.st.com/trademarks](http://www.st.com/trademarks). All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2023 STMicroelectronics – All rights reserved