

STEVAL-CCA044V1 board limitation


Board identification

This errata sheet applies to some samples of the STMicroelectronics STEVAL-CCA044V1, see the below information for details.

Table 1: Board summary

Part number	Device info	
STEVAL-CCA044V1	Error on Silkscreen (see Figure 1), if it is indicated:	
	PLAY	STBY OFF
	MUTE	STBY ON
	With this order	

Figure 1: Board identification



See the circle

1 Limitation

1.1 Silkscreen error

1.1.1 Part number affected

Preliminary sample of STEVAL-CCA044V1.

1.1.2 Description

These boards have an errata silkscreen, the correct one is:

MUTE	STBY ON
PLAY	STBY OFF

1.1.3 Workaround

Use the switch in opposite way.

2 Revision history

Table 2: Document revision history

Date	Version	Changes
19-Sep-2017	1	Initial release.

IMPORTANT NOTICE – PLEASE READ CAREFULLY

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2017 STMicroelectronics – All rights reserved