



History:

1.4 version, 2011-04-28

- 1) Update SPC563964L7 pin assignment in schematic library and schematic to be compatible with Andorra (SPC5644R7L).
- 2) Update VDD (1.2 core digital supply) circuit according to reference manual.
- 3) Add 1pcs L9616 (UB) and related resistors and jumpers to support one more CAN channel (CAN_B).
- 4) Change edge connector 35*4 -> 36*4 to support additional eMDS/eTRU/GPIO channel of Andorra.
- 5) Correct some type of pin name.

1.4.1 version, 2016-03-23

- 1) Correct 'hexus' block pin names, also relative net names